

Manhole Inspection Summary

Manhole # S55GG_003MH

Printed On: 6/24/2010

Page 1 of 4

Inspection Is Incomplete Rating: **2) Good**

Record Plat: **55GG** Node: **003** Status: **Not Found**

Insp Date: **2/16/10 2:46 PM**

Incomplete Comments

Crew: **REI2**
Inspector: **Provine, D**
Firm: **JV**

Location Address: **3800 Biddle St.**

Cross Street: **Chase St.**

Manhole Type: **Inline** Location: **Easement / Right of Way**

Ground Conditions: **Dry**

Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments **Pass**

Cover Shape: **Circular** Diameter: **24** (in.) Length: (in.) Dist A/B Grade: **12** (in.)

Type: **Sanitary** Condition: **Sound** Cover Material: **Cast Iron**

Properties: Bolted Vented Water Tight Water Tight Insert

Frame Offset: **0** (in.) Condition: Sound Cracked **Leaks**

Chimney / Frame Adjustment Exists Material: **Brick** Parged Height: **12** (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Corbel Material: **Brick** Parged Type: **Concentric/Eccentric**

Condition: Sound Cracked **Root Intrusion** Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar **Roots** Wall

Barrel Material: **Brick** Parged

Shape: **Circular** Diameter: **67** (in.) Length: (in.)

Condition: Sound Cracked **Root Intrusion** Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar **Roots** Wall

Bench Exists Material: **Brick** Parged

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Channel Material: **Brick** Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Steps Count: **4** Missing: **0** **Corroded**

Surcharge Evidence Of Surcharge Depth: (ft.) Active Surcharge Present

Location View



Location View



Location View



Location View



Top View



Top View



Top View



Defect 1



steps

Manhole Inspection Summary

Manhole # S55GG_003MH

Printed On: 6/24/2010

Page 4 of 4

24 in. Circular Gravity Sewer
Pipe Out @ 12 O'Clock

12 O'Clock Outflow



Pipe Height: **27.6** (in.) Rod and Bar (Angled)
Pipe Material: **Clay** Pipe Lined
Invert Depth: **11.50** (ft.) Flow Characteristics: **Slow**
Deposits: None Mud Sludge Debris Grease
Silt Depth: (in.) Deposits Extent:
Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**
 Possible Illicit Connection

24 in. Circular Gravity Sewer
Pipe In @ 6 O'Clock

6 O'Clock Inflow



Pipe Height: **27.6** (in.) Rod and Bar (Angled)
Pipe Material: **Clay** Pipe Lined
Invert Depth: **11.42** (ft.) Flow Characteristics: **Slow**
Deposits: None Mud Sludge Debris Grease
Silt Depth: (in.) Deposits Extent:
Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**
 Possible Illicit Connection